

Dean Smith & Grace
LIMITED
KEIGHLEY ENGLAND

**OPERATOR'S
INSTRUCTIONS**

TYPE	LATHE	MACHINE No
------	-------	------------

GENERAL NOTES

Ample and proper lubrication is essential to ensure good results and lasting accuracy. Lubrication of the lathe should start as soon as it has been cleaned and before any mechanisms are operated or sliding parts moved. Do not fill oil wells above the level shown on the oil sight, and use only high grade oil with an equivalent specification to that given on the chart. If difficulty is experienced in maintaining turning, facing and boring operations to within standard limits, the chances are that this is caused by the lathe being out of level. Most complaints of this nature have been found to be due to this cause, and the lathe should be carefully re-levelled, using a good sensitive level. Plain Bearing Head Lathes should not be used at the top spindle speeds until a few days' heavy work has been done on the slower speeds. After this, when using the top speeds, the lathe should be first started up on a slower speed to warm up the headstock parts. Hammers, spanners, tools, etc., should not be placed on the bed, shears or slides. This prevents scratching and other damage to the same. When removing or replacing the chuck, place a board on the bed to protect the ways from bruising.

CAUTION.—Do not change spindle speeds or feeds with the shafts revolving any faster than is necessary to engage the gears properly; the lathe should be slowed down or stopped to do this. When stopped, if the gears do not mesh instantly the friction clutch should be lightly engaged to revolve the gears slowly.

CHATTER.—May be due to the following causes and these should be checked over before asking for a service call —


- Work extending too far from chuck, change method of chucking or supports outer end in stay or with tailstock centre.
- Too great a distance between centres without support; use a stay.
- Oil, grease or dirt in between spindle nose and flange and chuck; these parts should be cleaned before mounting chuck on the spindle.
- Dirt between centres and workpiece or bad fitting centres in fast headstock or tailstock.
- End play in spindle.
- Improperly adjusted compound rest and saddle slips or gib plates.
- Cutting edge of tool below centre of spindle.
- Tool too weak or having too much overhang.
- Tool insecurely clamped in tool-rest.
- Irregular shaped work and fixtures causing out of balance or intermittent cutting.
- Incorrect selection of cutting speed and feed.
- The preload of the spindle bearings may be too low. This preload should be checked against the figure given on the bearing adjustment sheet, and any necessary adjustment made.
- Wipers for bed shears should be cleaned frequently and adjusted or replaced as required.

SPARES.—When ordering spares, clear descriptions or sketches of parts should be given, and in all cases it is important to quote the machine number given on the lathe nameplate or end of bed shears.

IMPORTANT

THIS MACHINE MUST NOT BE CLEANED DOWN BY USING AN AIRLINE. CONTRAVENTION OF THIS INSTRUCTION MAY PREJUDICE THE MACHINE WARRANTY.

LIFTING AND LEVELLING INSTRUCTIONS



LIFTING:—When lifting, a sling should be placed around one or two of the middle rings of the bed between the guiding ways and another sling around the ends of a steel bar passing through the holes provided in the bed. The saddle should be placed in a suitable position for balancing. The slings should be packed clear of parts liable to damage, such as feedshaft, etc.

LEVELLING:—The Lathe should be set with adjusting screws setting on plates and with bolts in position, the holes then being filled in. After the concrete holes are set levelling is accomplished by means of the adjusting screws in each foot and using an accurate spirit level (0.0005" in 10').

The level should be placed crosswise on saddle top and lengthwise on the back shear of the bed, the saddle being moved along the bed for checking crosswise at the different positions. The bed should be levelled initially in the crosswise direction and from end to end in the lengthwise direction using the front and rear adjusting screws at extreme ends of lathe only. Move the saddle up to the chuck, tighten the front screw at "A" until the bubble in the level just moves (i.e. 1/2 divisions if level read 0.0005" per division in 10') and bring back to level using corresponding rear screw.

Should the lathe have extra feet then it should now be levelled with the saddle immediately over each foot in turn, in crosswise and lengthwise direction at these points.


NOTE:—Locknuts on adjusting screws should be tightened immediately after each adjustment. It is also desirable to keep the machine as near the floor as possible. Greasing is not recommended as this causes inconvenience when re-levelling. Before commencing the lathe should be fully oiled to instructions given on separate sheet.

Take a finishing cut along a bar projecting 12" from the Chuck and check diameter by micrometer. The bar should be parallel to within .0004" in 9'. If outside this limit, check on top and sides of bar using a dial indicator from saddle as parallelism of spindle test on inspection sheet, allowing for taper of bar. Adjust levelling screws at extreme LEFT HAND END of the bed only to correct any inaccuracy. Take a further light cut to check result.

When levelling and turning tests are correct the holding down bolts should be tightened ensuring that the level is not disturbed. At no time should levelling be corrected with the holding down bolts nipped tight.

It should be realised that the whole purpose of the levelling operation is to endeavour to reproduce the conditions under which a lathe has been built and inspected at D.S.G. works. Here all testing is done with the bed levelled but not bolted down and, therefore, free from stress. Although there is no provision for mounting a spirit level on the Fast headstock, parallelism of spindle test on Inspection Sheet fulfills this function and if repeated after installation, as explained above, should assure correct alignment of headstock and bed. The level of the lathe should be checked periodically, say every 6 months.

IDENTIFICATION CHART



1. Feed and screw reverse lever.
2. Spindle speed change and reverse levers.
3. Coarse pitch operating lever.
4. Push-button unit.
5. Work steady for bar work.
6. Feed change lever on end-gearbox.
7. Change wheel cover.
8. Lead screw engaging lever.
9. Feed change lever and knob.
10. Slip coupling for feed shaft.
11. Clutch and brake operating levers.
12. Removable gap piece.
13. Saddle handwheel.
14. Square turner locking and operating lever.
15. Apron handwheel.
16. Compound rest handle.
17. Operating lever for lead screw.
18. Screwcutting dial.
19. Sliding and surfacing feed change lever.
20. Apron oiling pump.
21. Feed engage and trip lever.
22. Saddle lock handle.
23. Wipers for bed shears.
24. Wiper for crosscock spindle.
25. Tailstock spindle lock handle.
26. Tailstock clamp lever.
27. Tailstock spindle hand-wheel.
28. Tailstock locking bolt.
29. Scaling screws for taper work.
30. Electric driving motor.
31. Motor adjusting screws.
32. Feed reverse lever.


RECOMMENDED LUBRICANTS

FOR ALL TYPES OF LATHE (EXCEPT NO)


ASSEMBLY	SHELL	CASTROL	MOBIL	GULF
HEADSTOCK	TURBO 52 VITREA 27	HYSPIN AWS. 32	D.T.E. 24	HARMONY ³² ■
THREAD & FEED GEARBOX	TONNA 33	MAGNA BD.	VACTRA NO. 2	GULFWAY 52
APRON, SADDLE & SLIDEWAYS	TONNA 33	MAGNA BD.	VACTRA NO. 2	GULFWAY 52
ELECTRICALLY OPERATED TURRET	TURBO 52 VITREA 27	HYSPIN AWS. 32	D.T.E. 24	HARMONY ³² ■
RELIEVING UNIT, INCLUDING Q/BOX	TONNA 33	MAGNA BD.	VACTRA NO. 2	GULFWAY 52
LUNZER INTEGRAL REVOLVING CENTRE	ALVANIA EP2	SPHEEROL EPL 2	MOBILPLEX 47	GULFCROWN NO. 2
HYDRAULIC COPYING UNIT	TELLUS 33	HYSPIN AWS. 68	D.T.E. 26	HARMONY 54 AW
OIL NIPPLES & OIL GUN	TONNA 33	MAGNA BD	VACTRA NO. 2	GULFWAY 52

NOTE THE NUMBER OF OILS HAS BEEN KEPT TO A MINIMUM. QUANTITIES & REGULARITY OF CHANGES ARE LISTED FOR EACH MODEL ON SEPARATE DIAGRAM & LUBRICATION SHEET,


CAPACITY CHART



ISBN 978-10 9114 383



INDIA, TACOS & TEA - 6 CUPS 4-35.00 LBS. INDIA TEA CANISTER



A - SWINGS IN GAP 27' DIA.
 B - SWINGS OVER AND COVERS 16' PIECE
 C - SWINGS OVER SADDLE GUARD 10' DIA.
 D - SWINGS ON THE SADDLE GUARD REMOVED 12' DIA.
 E - TURNING MAX. LENGTH = 12' 15"
 F - TURNING MAX. ANGLE = 90°, TURN UNTIL
 G - TURNING MAX. ANGLE = 90°, TURN UNTIL

SADDLES AND SLIDES

The saddle is locked to the bed by means of the lever on the top of the right-hand saddle wing, this should, if possible, be locked when surfacing.

The top slide can be locked by means of the square-headed screw at the front of the top slide.

Each division of the saddle-screw dial represents .001 in. movement of the tool, likewise the tool moves .001 in. per division of the top slide dial.

There are felt wipers at the ends of the bed shear covers and these should be renewed as required.

THE SQUARE TURRET

This is of the automatic type and anti-clockwise movement of the lever unlocks the turret, lifts the locating plunger and rotates the turret to the next station; the locking motion is of course reverse to this. The turret can be locked in intermediate positions when this is necessary. The dimensions of the turret and the tool size are given on the capacity chart.

TAILSTOCK

The position of the spindle clamping lever can be adjusted by slightly turning the nut with 2 tommy holes at the bottom of the clamping bolt.

Slight long tapers can be turned by offsetting the tailstock from its shoe with the screws provided.

To remove the centre retract the spindle fully when the centre will be automatically ejected.

The cover at the end of the tailstock carries a felt wiper for keeping the spindle and bore clean: this should be renewed when necessary.

THE MOTOR DRIVE

This is by a flanged motor and vee-rope drive. For adjustment of ropes the motor is mounted on an adaptor plate with 4 bolts engaging slots in the main motor support bracket. To adjust, it is only necessary to slacken the fixing nuts and lower by the adjusting screws provided.

THE ELECTRIC CONTROL PANEL

If necessary, this can be easily removed by disconnecting the wires at the panel from the switch and push-button station and taking out the screws in the fixing straps, when the panel will pull out. Switch off at the isolating switch before removing the cover over the panel chamber.

FAST HEADSTOCK


The motor is started and stopped by means of the push buttons on the control unit on the fast headstock; these operate the starting panel. Spindle speeds are obtained by means of the set of 3 operating levers at the front, the speeds being self indicating. The spindle should be stopped by means of the clutch-operating lever before changing speeds.

Feed reverse and coarse pitch operating levers are also situated at the front of the headstock.

A work steady for supporting bar work is fixed at the extreme end of the spindle and is fitted with 4 Allen grub screws for gripping the work.

The clutch and brake through which the drive is taken on the pulley shaft are self adjusting and should need no attention, if trouble however does occur our advice should be sought.

OILING DIAGRAM



Use Shell Vivers 2
or equivalent oil.
Specification as follows.

} Specific gravity .86
Flash point closed 400°F.

Viscosity at 100°F
Viscosity Index—

{ 150 Redwood Sec (D63 U.)
170 Saybolt
95

Use Shell Tonna 2.
Vacuum Vacra No. 2 or
Equivalent oil
Specification as follows

} Specific Gravity .875
Flash point closed 400°F.
Containing non-drip, anti-wear and oiliness additives

Viscosity at 100°F { 200 Redwood Sec (D63 U.)
220 Saybolt
95

TABLEWAY OIL FOR APRON, GEARBOX AND OIL GUN

CHANGE OIL IN FAST HEADSTOCK, AND GEARBOX EVERY 6 MONTHS.

FAST HEADSTOCK (8 Pines)
Fill and keep to centre of oil sight "B"
(through cap "C" when sight is stopped).
Oil by pump at "A" through pipe.
This combined mechanical and magnetic filter
should be removed and both
elements cleaned monthly, and always
when changing oil.

To drain, remove the combined filters
unit and pump out oil through the
bottom; alternatively, drain by gravity
through the bottom plug. To prime
pump, remove hangon plug inside
the headstock.
Oil sight "D" indicates when oil pump
is functioning.

GEARBOX (7 Pines)
Fill and keep to centre of oil sight "E"
(through cap "F" when sight is stopped).

Drain at plug "G". Top oil sight indicates
when pump under cover "S" is working

APRON (2 Pines)

Fill and keep to centre of oil sight "H"
through cap "I" on saddle. Oil sight
"K" indicates when pump "L" is
working.

Drain at plug "M".

To prime oil pump remove plug behind
spring (No. 9 spare parts list).

Oil thread indicator drifts through nipple
below dial.

BED WAYS

Apron pump lubricates bed ways suc-
cessfully and due to this, the apron
requires "Topping-up" at regular inter-
vals.

In the event of failure of supply to bed
ways, check filter by removing screw

plug in end of filter connector bracket
at R.H. end of apron.

TOP SLIDE NUT

Oil top slide screw nut by removing
cover "N".

SADDLE SCREW NUT

Oil daily through nipple "R" on top of
saddle.

SLIDE VEES

Oil daily through nipple provided on
slide.

GENERAL

All other points should be oiled weekly
through the nipples indicated by red
washers using the oiling gun provided.
There are 2 (two) oiling points under
cover "S".

Note—Grease must never be used
in the oil gun.

INSTRUCTIONS FOR USE OF SCREWCUTTING DIAL

This is a most useful aid to screwcutting although its use is limited to certain threads and pitches. Where applicable it enables the nuts to be engaged without danger of cross threading. The dial may be used when cutting any pitch which is contained a whole number of times in a length of 8 in. From this it will be seen that the whole numbers of threads per inch can be cut, also threads per inch ending in eighths, quarters and halves, viz. $2\frac{1}{2}$, $2\frac{1}{4}$, $2\frac{1}{2}$ t.p.i. One revolution of the dial is equivalent to 8 in. length of thread on the screw. As the dial is divided into 16 divisions, the alternate ones being numbered 1 to 8, then from one numbered division to the next is $\frac{1}{8}$ of a revolution and is equivalent to 1 in. of screw thread. It will be seen therefore, that when cutting a screw having a whole number of threads per inch, the spindle will make a whole number of revolutions in one inch length, and as the leadscrew likewise makes a whole number of revolutions in the same distance the leadscrew nuts can be engaged at any numbered division on the dial. From this it follows that if the threads per inch in the screw to be cut is an even number, a whole number of threads is contained in $\frac{1}{8}$ in. and the nuts may be engaged at any of the 16 divisions on the dial. Similarly odd numbers can only be engaged at any numbered division, threads ending in halves engaged every quarter revolution of the dial, threads ending in quarters every half revolution; threads ending in eights every revolution. For linear inch pitches, convert the pitch to an equivalent number of threads per inch (viz. $\frac{1}{2}$ inches pitch = $1\frac{1}{2}$ t.p.i.) and follow the above rules. If the number of t.p.i. is neither a whole number nor does not end in $\frac{1}{2}$, $\frac{1}{4}$ or $\frac{1}{8}$ then the dial cannot be used, in which case the screw must be cut completely without disengaging the nuts and by using the screw reverse mechanism, or spindle reverse to run the saddle back with the nut engaged. There are certain other special applications of the dial and information on any particular case will be supplied by our technical department on request.

SCREWCUTTING INSTRUCTIONS

When setting the change gears it is important that there should be a small amount of backlash between each set of gears. This ensures that the drive to the screw will be smooth and that no undue stress is set up on the change gear studs which might lead to breakage. No difficulty should be met with in mounting the change gears if they are set as shown in the diagram on the plates. If the screwcutting motion has been standing for any length of time all the parts concerned should be lubricated together with the change gears.

Reverse to the screw for normal pitches is by the reverse lever on the front of the fast headstock operating a single tooth clutch running at the same speed as the spindle. Consequently the clutch may be used to run back the saddle to the starting position when cutting metric or odd pitches. This reverse lever should not be operated at speeds above 140 r.p.m.

Alternatively the spindle may be reversed by the lever on the head and the saddle traversed back at a quicker speed if desired.

Coarse pitches are obtained by means of the coarse pitch operating lever on the headstock which causes the gearbox drive to be taken from a driving shaft in the headstock instead of from the spindle. Reverse for screwcutting when using coarse pitch motion must be by reversing the spindle.

For accurate screwcutting it is essential that all slides should be adjusted properly without backlash and locked when possible.

As the leadscrew thrust is taken on ball bearings, there should be no wear, and if there is any slackness it will be caused by the checknuts becoming loose. These can easily be examined and adjusted if necessary.

When cutting very coarse leads, the nuts should be engaged and disengaged with the lathe stopped, using the driving clutch to start and stop the saddle traverse. The top slide should also be locked during each cut to obviate any digging of the tool due to the large helix angle of coarse lead screws.

As the rack pinion and handwheel shaft are mounted on ball or roller bearings no adverse effect on the screwcutting is experienced from drag of the pinion in the rack.

The leadscrew motion should be disconnected when not in use.

CLEANING OR REPLACING LEADSCREW NUTS

This is easily done by removing the thread indicator bracket from the side of the apron when the nuts will pull out.

TOTALLY ENCLOSED GEARBOX

This totally enclosed box has 24 changes, which, together with 2 change in the rear end gearbox gives 48 changes of feed and 48 different threads without alteration to change gears. The lever at the top right-hand end is used for disconnecting the leadscrew for short intervals. NOTE.—If the screwcutting motion is not being used for a long period the change wheels should be swung out of mesh.

NOTE.—To operate the top gearbox feed change knob, the gearbox should be run slowly and the bottom feed change lever put into neutral position.

A safety spring-loaded coupling transmits the feeds through the long feed shaft to the apron. The slipping load is pre-set and cannot be adjusted.


Feeds coarser than those shown on the chart can be obtained by engaging the coarse pitch ratio. This increases the feed by the coarse pitch ratio. These very coarse feeds can only be used on the lower half of the speed range, and should be used with discretion.

Longitudinal feeds coarser than .020 ins. or cross feeds coarser than .010 ins. should not be used above 120 r.p.m.

Cross feeds are half the Longitudinal feed numbers, i.e., half the feed in inches. Change wheels for all standard types of thread are shown in the accompanying chart, together with the necessary formulae for obtaining the change gears for special threads and pitches.

LUBRICATION.—See oiling chart.

TYPE 15	1	2	3	4	5	6	7	8	TYPE 17
THREADS PER INCH	2	2 ^{1/2}	2 ^{1/4}	2 ^{1/3}	2 ^{1/2}	3	3 ^{1/2}	3 ^{1/4}	CHANGE WHEELS
LONG- ITUDINAL FEEDS IN INCHES PER REV.	.0700	.0625	.0560	.0510	.0450	.0475	.0435	.0400	SCHMIDT
	.0350	.0310	.0280	.0250	.0210	.0235	.0214	.0204	INT'L STUD
	.0175	.0160	.0140	.0125	.0120	.0115	.0107	.0100	SOI
	.0087	.0065	.0070	.0063	.0055	.0058	.0054	.0054	1110 5422P
	.0045	.0040	.0035	.0032	.0020	.0028	.0027	.0023	NOI
	.0021	.0020	.0017	.0016	.0015	.0013	.0013	.0012	
FOR CROSS FEEDS DIVIDE THE NUMBERS BELOW BY 2									
LONG- ITUDINAL FEEDS IN INCHES PER REV.	.0350	.0310	.0280	.0250	.0210	.0235	.0214	.0204	
	.0175	.0160	.0140	.0125	.0120	.0115	.0107	.0100	
	.0087	.0065	.0070	.0063	.0055	.0058	.0054	.0054	
	.0045	.0040	.0035	.0032	.0020	.0028	.0027	.0023	
	.0021	.0020	.0017	.0016	.0015	.0013	.0013	.0012	



SCREW PITCHES IN INCHES									
COARSE PITCHES				NORMAL PITCHES					
SET 10 T.P.I.	CHANGE GEARS	SET 10 T.P.I.	CHANGE GEARS	COARSE PITCH	NORMAL PITCHES	SET 10 T.P.I.	CHANGE GEARS	SET 10 T.P.I.	CHANGE GEARS
2	4 8 N P R S	2	4 8 16 32 64 N P R S	120	65	120	65	120	65 30
3	1 1/2 3 6 12 24	1	1/2 1/3 1/4 1/5 1/6 1/8	123	73	125	63	120	50 40
4	1 1/2 2 4 8 16 32	1/2	1/2 1/3 1/4 1/5 1/6 1/8	128	60	128	60	128	50 40 60 50
5	1 1/2 2 4 8 16 32	1/2	1/2 1/3 1/4 1/5 1/6 1/8	110	55	122	51	122	55 30
6	1 1/2 2 4 8 16 32	1/2	1/2 1/3 1/4 1/5 1/6 1/8	100	50	120	50	120	45 30 40
7	1 1/2 2 4 8 16 32	1/2	1/2 1/3 1/4 1/5 1/6 1/8	90	45	118	48	118	45 30
8	1 1/2 2 4 8 16 32	1/2	1/2 1/3 1/4 1/5 1/6 1/8	80	40	116	40	116	40 50
9	1 1/2 2 4 8 16 32	1/2	1/2 1/3 1/4 1/5 1/6 1/8	75		115	75	115	45 60
10	1 1/2 2 4 8 16 32	1/2	1/2 1/3 1/4 1/5 1/6 1/8	70	35	114	7	114	35 50
FOR PITCHES NOT SHOWN ABOVE									
$\frac{N}{S} \text{ OR } \frac{N \times R}{P \times S} = \frac{\text{PITCH READ.} \times \text{T.P.I. SET FOR}}{1} \quad (\times 10 \text{ FOR COARSE PITCH})$									

SCREW PITCHES IN MILLIMETRES									
SET 10 T.P.I. TO THESE T.P.I.						CHANGE GEARS			
4	8	16	2	4	8	16	32	64	N P R S
120	65		120	65	32	125	63	120	65 30
123			123	73	125	63	123	60	50 40
128	60	30	128	60	32	126	6	125	75 60 50
110	55		110	55	22	111	55	110	55 30
100	50	25	100	50	20	10	5	125	63 45 40 40
90	45		90	45	18	9	4.5	225	63 40 45 30
80	40	20	80	40	18	8	4	2	115 60 40 50
75			75	75	75	75	75	75	45 60
70	35		70	35	14	7	3.5	175	63 40 35 50
FOR PITCHES NOT SHOWN ABOVE									
$\frac{N}{S} \text{ OR } \frac{N \times R}{P \times S} = \frac{53 \times \text{PITCH READ.} \times \text{T.P.I. SET FOR}}{1600} \quad (\times 10 \text{ FOR COARSE PITCH})$									

TOTALLY ENCLOSED GEARBOX

(Continued)

An alternative method of finding change gears for threads and pitches not on the charts is to select a thread or pitch near to the one required, from the appropriate chart, and modify the change gear ratio given on the chart in proportion to the thread or pitch required.

Ratio required =

$$\frac{\text{Gear ratio on chart} \times \text{Pitch required}}{\text{Pitch selected}} \quad \text{or} \quad \frac{\text{Gear ratio on chart} \quad \text{T.P.I. selected}}{\text{T.P.I. required}}$$

MODULE PITCHES										B.A. THREADS.															
SET TO T.P.I.		CHANGE GEARS			SET LEVERS TO THESE T.P.I.					CHANGE GEARS			B.A. THREADS.												
4	6	8	10	12	2	3	4	6	8	16	32	N	P	R	S	N	P	R	S	N	P	R	S		
COARSE MODULE												N P R S													
12	16	20	30	40	50	8	12	16	20	32	64	60	50	40	32	63	40	32	63	40	32	63	40	32	
30	20	15	60	40	45	50	8	4	2	1.5		62	35	55	50	9	9	40	63	40	45	50			
28	16	55	50	60	50	7.5	5	3.75	2.5	1.875		66	40	45	40	2	81	32	50	35	45	63			
26	13	45	60	30	35	7	3.5	3.5	2.75	1.875		68	40	63	60	3	71	32	63	43	35	55			
24	16	12	45	50	60	50	6.5	3.25	2.5	1.625		50	35	45	40	4	66	40	45	63	80	40			
22	11	60	35	40	83	5	4	3	2	1.5	1.25	1.25	68	40	45	50	5	59	80	63	50	40	35		
20	10	45	50	60	60	5.5	2.75	2.75	1.875			60	35	50	63	6	51	44	63	40	35	60			
18	12	9	63	45	35	55	5	2.5	1.25	0.625		66	40	45	60	7	48	40	45	55	60	65			
FOR PITCHES NOT SHOWN ABOVE												B A 42 36 45 38 40 50													
$\frac{N \text{ OR } N \times R}{S \text{ OR } P \times S} = \frac{\text{MODULE PITCH REQUIRED} \times \text{T.P.I. SET FOR } X 99}{800 \text{ (X 10 FOR COARSE PITCH.)}}$												9 39 80 80 40 45 55													
10 35 80 63 40 35 50																									

DIAMETRAL PITCH CHART												OTHER THREADS											
COARSE CHANGE GEARS		NORMAL DIAMETRAL PITCHES										LEVER		NORMAL CHANGE GEARS		CHANGE GEARS							
S	SO	4	1/2	5	3 1/2	5 1/2	6	6 1/2	7	A	B	D	S	15	SCREW	S	15	SCREW	S	15	SCREW		
S	SO	8	9	10	11	11 1/2	12	13	14	B	D		S	15	SCREW	S	15	SCREW	S	15	SCREW		
15		16	18	20	22	23	24	26	20	C			T.P.I. OBTAINED	4 1/2	9 1/2	19	38	40	50	38			
P	R	37	38	40	44	46	48	52	56	A	E		SET TO T.P.I.	2 1/2	10	20	40	N	15 1/2	S			
N		61	72	80	88	92	96	104	112	B			T.P.I. OBTAINED	2 1/2	10 1/2	21	42	60	40	63			
SS		1	1 1/2	1 1/2	1 1/2	1 1/2	1 1/2	1 1/2	1 1/2	A	D		SET TO T.P.I.	12	24		N	15 1/2	S				
		2	2 1/2	2 1/2	2 1/2	2 1/2	1	3 1/2	3 1/2	C			T.P.I. OBTAINED	12 1/2	27		40	50	45				
		1	2	3	4	5	6	7	8				SET TO T.P.I.	6	12	24	48	N	15 1/2	S			
													T.P.I. OBTAINED	7 1/2	15	30	60	40	55	50			

INSTRUCTIONS FOR CUTTING MULTIPLE START SCREWS

For all multiple start screws the coarse pitch ratio must be engaged to use the following method of dividing.


The starts can be obtained by marking the spindle or chuck flange and the main headstock, the spindle or chuck flange being divided into the number of starts required. Then 2, 3, 4, 6, or 8 starts can be obtained by pulling out of engagement the driving pinion (shown in sketch), operated by means of the lever giving fast and slow speed ranges on the fast headstock, and leaving the lever in the neutral position approximately as shown.

The spindle is then turned the requisite amount and the pinion can then be re-engaged; care should be taken not to disturb any other motion whilst this is being done. As the gear on the spindle has 72T, any number of starts which will divide into 72 can be cut in this way.

To obtain 5 or 7 leads proceed as above but disconnect gearing by moving coarse pitch lever back into neutral instead of the fast—slow spindle speed lever. This engages a 35T gear which divides by 5 or 7, as this gear runs 10 times faster than the spindle it is necessary to be accurate in marking the chuck for the number of leads required.

Before dividing, all backlash should be removed, with the work and leadscrew turning in the direction of cutting.

Information on any particular case will be supplied on request by our technical department.



When using the coarse pitch ratio for leads of 1 in. and under or 25 mm. and under, the gearbox levers should be set to 10 times the t.p.i. indicated at the top of the column containing the desired lead on the screw pitch chart.

INSTRUCTIONS FOR TAPER TURNING

This attachment will turn taper work up to 4 inches per foot on diameter or 20° included angle.


When tapering it is only necessary to set the guide bar at the required angle. The guide bar is locked by means of the 2 nuts exposed on removing the plugs from the bar. The 2 Allen socket head screws in the guide block should also be locked when tapering. The saddle screw is located in the guide block by ball thrust bearings, and being telescopic with its driving pinion pushes or pulls the cross slide with it; thus adjustment to the cut can be made in the ordinary way by means of the saddle screw handwheel and dial.

There should be no backlash on the saddle screw nuts, and adjustment to these can be made by grinding the setting plate, which is slotted to lift off, by merely slackening the 2 Allen fixing screws. Before doing this the backlash should be measured by means of the saddle screw dial, taking into account the backlash between the key and keyway of the telescopic joint. The saddle vee guard can be removed by slackening back the 2 grub screws marked (A) on diagram, which hold the guard fixing pins.

The knurled knob for setting the taper should only be used with the long guide bar approximately central with the saddle screw otherwise it will be difficult to operate.

IMPORTANT.—The swivelling guide bar and guide block must be always locked by the two end bolts and the 2 Allen screws after making any adjustment to it, even though the taper attachment is not in use, as the bar takes the thrust from the saddle screw.

If the motion has been standing see that it is well cleaned and lubricated before use.



INSTRUCTIONS FOR CUTTING MULTIPLE START SCREWS

(Continued)

For example, the levers should be set to 20 c.p.i. or 40 c.p.i. for $\frac{1}{2}$ in. lead or $\frac{1}{4}$ in. lead respectively and use the change wheels indicated for these leads.

When using the coarse pitch ratio for multiple start screws designated in c.p.i., for example 12 c.p.i. 3 starts, the gearbox levers should be set to the c.p.i. on chart found in the following manner:—

$$\text{c.p.i. on chart} = \frac{\text{c.p.i. of work} \times 10}{\text{Number of starts}}$$

If the c.p.i. thus found is not on the chart, convert the same c.p.i. to an equivalent inch pitch.

The change gears required, if not on the chart for screw pitches, may be found from:—

$$\frac{N}{S} \text{ or } \frac{N}{P} \times \frac{R}{S} = \frac{\text{Pitch required} \times \text{c.p.i. set for}}{1}$$

Example 1.—To cut 4 starts 8 c.p.i.:—

$$\text{c.p.i. on chart} = \frac{8 \times 10}{4} = 20 \text{ c.p.i.}$$

Therefore set levers to 20 c.p.i. and coarse pitch.


Example 2.—To cut 3 starts 8 c.p.i.:—

$$\text{c.p.i. on chart} = \frac{8 \times 10}{3} = \frac{80 \text{ c.p.i.}}{3} = 3/80 \text{ in. pitch.}$$

$$\text{Change gears} = \frac{3 \times (20 \text{ c.p.i. set for})}{80} = \frac{3}{4} = \frac{45}{60}$$


Therefore set levers to 20 c.p.i., also to coarse pitch and use change gears N/S = $\frac{45}{60}$ or $\frac{30}{40}$

INSTRUCTION SHEET FOR DISMANTLING AND REASSEMBLING CROFT'S PATENT B.O.M. L TYPE CLUTCH MECHANISM



OIL IMMERSED TYPE.

NOTE: NOTE OF LIPSE WASH.
LEAD UP TO SMALL FLAT
SURFACE ON BACKPLATE.



NOTE: NOTE OF LIPSE WASH.
LEAD UP TO SMALL FLAT
SURFACE ON PRESSURE PIECE.

DISMANTLING
PRESSURE PIECE ASSEMBLY "F"

TO DISMANTLE CLUTCH MECHANISM

1. Withdraw mechanism complete from shaft.

2. Put clutch into out of gear position.

3. Remove spring ring "N" using pointed tool for sprung out of groove.

4. Remove distance washer "P".

5. Withdraw clutche reaction plate "L".

6. Remove operating ball "H".

7. Withdraw pressure distance plate assembly "F".

8. Withdraw driving discs "C" and "D" and backplate "B" from sleeve "A".

TO REASSEMBLE CLUTCH MECHANISM

10. Before reassembling, clean all parts carefully and lubricate slightly.

11. See that withdrawl keys "E" are in position in sleeve "A".

12. Replace backplate "B"; see that this is correct way round.

13. Fit outer driving disc "C" followed by inner driving disc "D" and so on alternately until complete number of discs are in position.

14. Inspect pressure distance piece assembly "F" and see that the correct number of different length springs "G" are in position, equally spaced, with the centre fulcrum pin at the outer end of the spring. (To hold spring in position, smear them with thick ball-bearing grease.)

15. Slide pressure distance plate assembly "F" into its position on sleeve "A".

16. Replace sliding collar "H", the flat side facing inwards key "I" is in position on collar and so fits with withdrawl keys "E" in sleeve "A".

17. Replace lock washers "K" and lubricate slightly.

18. Replace lock washers "L" on sleeve "A".

19. Place sliding collar "H" in "out of gear" position.

20. Replace distance washer "P" on sleeve "A" and spring ring "N" in groove.

21. Align teeth on all discs and put clutch into "in gear" position.

TO DISMANTLE PRESSURE PIECE ASSEMBLY "F".

Clamp the pressure distance piece assembly to a bench or vice by means of a bolt, and compress the springs "G" until the spring "R" can be removed. Remove spring ring "R" and gradually relax pressure on spring by releasing clamping bolt. The outer portion may then be removed and new spring fitted.


If the full number of prints are not fitted, care must be taken to see that opposite spaces are left without spring so that the pressure of the spring will be properly balanced.

The distance piece may be assembled by compressing spring with clamp as mentioned above, care being taken to see that the spring ring "R" fitted down in the groove correctly.

CROFTS (ENGINEERS) LTD,
BRADFORD

LIST N°
8291

F.
R.
24



To TRANSMIT 1-0 H.P. AT 100 R.P.M.

LIST N°
8291

N^o 2 PATENT L TYPE BOM.C CLUTCH.
OIL IMMERSSED TYPE.

DATE:-
30-10-45


CROFTS (ENGINEERS) LTD.
BRADFORD

LIST NO.

20671

P.L.S.
REF.
32

SIZE OF CLUTCH	CLEARANCE
1	0.30"
2	0.30"
3	0.30"
4	0.30"
5	0.40"
6	0.40"
7	0.40"
8	0.40"



CLUTCH & BRAKE TO BE CLAMPED IN POSITION SHOWN & BRAKE PORTION TO BE TESTED FOR BRAKE CLEARANCE AS ILLUSTRATED SURFACE 'A' OR 'B' TO BE GROUND TO SUIT CLEARANCE GIVEN IN TABLE.

ST NO
20671

METHOD OF ADJUSTING DISC BRAKE
ATTACHMENT FOR 'L' TYPE 8.0M. CLUTCHES.

DATE
19.5.66.

INSTRUCTIONS FOR SPINDLE BEARING ADJUSTMENT

PLAIN BEARING SPINDLE

Before starting up the spindle, the motor should be set on and left to run a few minutes to allow oil to circulate around all bearings, especially the front bearing. For the first few weeks it is advisable to run the head by steps up to the top speeds if they are required. If in any difficulty consult us for advice.


The spindle bearings should not require adjustment for some years if the oil in the head has been renewed with clean oil periodically. (See oiling diagram.)

BEARING ADJUSTMENT

1. Remove set screw in nut "C" and adjust nut until torque to turn spindle when in neutral position is 30-40 lb. in. Torque can be measured by the pull on a light spring balance attached to a string carried around the lathe chuck, turning the spindle slowly.
2. Remove chuck and measure accurately to .001 in. distance "X" between flange of spindle and machined face of cover "E".
3. Slacken nut "C" about four turns and knock spindle forward until rollers of bearing "D" are clear of outer race.
4. Remove two halves of ring "A" after taking out screws "B". Take care not to bruise faces of ring.
5. Tighten nut "C" and at the same time turn spindle to squeeze out oil from front bearing until spindle can only just be moved by chuck key. Knock inner race of bearing "D" forward so that rollers clear outer race.
6. Measure new distance "X". Add to this size .007 in. and subtract the sum from first measurement of "X". The remainder is the amount to be machined of the width of split ring. The ring faces must be parallel to .0005 in.
7. Slacken nut "C" two turns and knock back the bearing "D" until split ring can be replaced and lightly fastened.
8. Replace chuck and tighten nut "C" until torque to turn spindle steadily is 40-50 lb. in. A new hole for the dog point of the set screw in nut "C" may be required. Tighten screws "B".

Note: The constant .007 in. gives the clearance for oil film thickness of .00037 in. in the front bearing, and correct torque ensures a proper bearing temperature.

INSTRUCTIONS FOR SPINDLE BEARING ADJUSTMENT (Continued)





ROLLER BEARING SPINDLE REFER TO SHEET 30

To obtain correct adjustment of taper roller bearings 74 and 76 (See spare parts sheet).

1. Remove set screw in nut 72 and adjust nut until torque to turn spindle is 40-50 lb.in. The torque can be measured by the pull on a light spring balance attached to a string carried round the lathe chuck, turning the spindle slowly.
2. A new hole for the dog point of the set screw in nut 72 may be required.

The torque given above should not be exceeded as this may cause overheating of the bearings.


SPARE PARTS LIST FOR FAST HEADSTOCK




1. H.A.H. L.S.10.—A. & M. L.1.11
2. H.A.H. L.S.10.—R. & P.C. L.1.11
3. Pulley shaft
4. 21T. 100.D.P. helical gear on 2nd shaft
5. Clutch shaft
6. Brake shaft
7. N.S.H. L.S.12.—A. & M. L.1.11
8. Intermediate
9. 21T. 100.D.P. gear on 1st shaft
10. 21T. 100.D.P. gear on 1st shaft
11. 21T. 100.D.P. gear on 1st shaft
12. 21T. 100.D.P. gear on 1st shaft
13. H.A.H. L.S.10.—A. & M. L.1.11
14. H.A.H. L.S.10.—A. & M. L.1.11
15. Axle shaft
16. 21T. 100.D.P. gear on reverse shaft
17. H.A.H. 131.—A. & M. L.1.33
18. H.A.H. 131.—A. & M. L.1.33
19. Helical reduction division on 2nd shaft
20. 2nd shaft
21. 21T. 100.D.P. gear on 2nd shaft
22. 21T. 100.D.P. gear on 2nd shaft
23. 21T. Double gear on 2nd shaft
24. H.A.H. L.S.12.—A. & M. L.1.11
25. H.A.H. L.S.12.—A. & M. L.1.11
26. 2nd shaft
27. 21T. 100.D.P. gear on 2nd shaft
28. 21T. 100.D.P. gear on 2nd shaft
29. 21T. 100.D.P. gear on 2nd shaft
30. H.A.H. L.S.12.—A. & M. L.1.11
31. Helical reduction gear on 2nd shaft
32. H.A.H. 131.—A. & M. L.1.33
33. SST. 100.D.P. helical gear on 2nd shaft
34. 2nd shaft
35. 21T. 100.D.P. gear on 2nd shaft
36. H.A.H. L.S.12.—A. & M. L.1.11
37. H.A.H. L.S.12.—A. & M. L.1.11
38. 21T. 100.D.P. gear on 2nd shaft
39. 21T. 100.D.P. gear on 2nd shaft
40. H.A.H. X.L.S.11.—A. & M. L.1.11
41. H.A.H. X.L.S.11.—A. & M. L.1.11
42. 21T. 100.D.P. gear on 2nd shaft
43. 2nd shaft
44. H.A.H. 131.—A. & M. L.1.33
45. SST. 100.D.P. helical gear on 2nd shaft
46. H.A.H. X.L.S.11.—A. & M. L.1.11
47. 21T. 100.D.P. clutch gear on 2nd shaft
48. Clutch sleeve or 2nd shaft
49. SST. 100.D.P. clutch gear on 2nd shaft
50. 2nd shaft
51. SST. 100.D.P. clutch gear on 2nd shaft
52. SST. 100.D.P. clutch gear on 2nd shaft
53. H.A.H. L.S.12.—A. & M. L.1.11
54. Timken axle. 3. cone 562 end 592B.
55. Plain bearing cones
56. Timken axle. 3. cone 563. end 592B.
57. Serrating collar on spindle
58. 21T. 100.D.P. helical gear on spindle
59. 21T. 8;D.10. gear on middle front neck bearing
60. Cone on front neck spindle nose
61. 21T. 100.D.P. cone outside hard
62. H.A.H. 131.—A. & M. L.1.33
63. Short feed shaft
64. 21T. 100.D.P. gear on short feed shaft
65. H.A.H. L.S.12.—A. & M. L.1.11
66. Feed lever on intermediate
67. Feed lever on intermediate
68. H.A.H. 131.—A. & M. L.1.33
(precision)
69. Roller bearing cones
70. Middle checknut on cone
71. SST. 100.D.P. radial hub on spindle
72. Timken axle. 3. cone 563. end 592B.
73. SST. 100.D.P. gear on spindle
74. Timken axle. 3. cone 563. end 592B.
75. Radial. Symbol No. 528

Type 19. DI-8' CARLOCK

SPARE PARTS FOR SADDLE AND SQUARE TURRET ON COMPOUND REST




SPARE PARTS LIST FOR TOTALLY ENCLOSED GEARBOX




ארכיטקטורה עירונית


SPARE PARTS LIST FOR APRON




1. Bars
2. Lead screw nut.
3. Lathe apron support bracket.
4. Thread indicator wheel
5. Pump eccentric
6. 30T & 27T. 12 D.P. sliding gear
7. Reverse position gear
8. Intermediate reverse pinion 27T
12 D.P.
9. Pump plunger spring
10. 16T 17 D.P. gear on worm
11. Feed worm 10 D.P., 2 lobes, L.H
12. 27T 12 D.P. gear on worm
13. Worm box.
14. Spring on trip shaft
15. Sliding trip shaft
16. Half 5 B — R. & M. L.L.
17. Hand racking shaft
18. Half 5 H — R. & M. L.L.
19. Rack, alumin. shaft.
20. Hoff, 130 D.H. — R. & M. L.D.J.16.
21. 89T. 12 D.P. gear.
22. 35T. A 65T. 12 D.P. sliding gear.
23. Chain for 15T & 65T. 12 D.P.
sliding gear
24. Feed reverse operating shaft
25. 38T. 10 D.P. worm wheel
26. 21T. 12 D.P. pinion



12 DISC/EVW NARIN & SCRIVCUTTING 244



NHP WARM BOX & TRIP MOTION



TYPES 15, 17, 20SB LATHES

AMERICAN SPINDLE NOSE TYPE D.I.

