



The screw has a fine knurl on the end and a 7/32 hex socket in the end.
 The main boss has a fine knurl from the top down to 5mm above the tapped hole.
 The only critical dimension is the diameter of the bore to suit the centre shaft.